

Photos of water turbulence below dam

690317-1 from W embankment showing general view. Apron to left.

690317-2 " " " " " " " " " " " "

Conoe entered turbulence at point $\frac{1}{3}$ up from bottom of picture.

690317-3 ibid

690317-4 ibid

(see page 690317-102)
for proper entry.