

The ♂ apparently was attracted by the copulating pose created by the off balance of the ♀.

June 13, 1969

noted a blue jay replace a starling which was perched on a wire.

Lawrence, Douglas Co., Kansas

June 13, 1969

Purchased trailer from Lawrence Badle (1218 Tenn, Lawrence)
Specifications: Trall Star (Starcraft) deluxe.

Price \$2000.00 plus \$35.00 regulator for electric brakes, plus tax.
length 17'2" weight 2220 lbs

width 7'11"

hitch weight 285 lbs

height 8'4"

tire 7.75 x 15"

serial number 68-TLD-113 license tag DL 464

appraisal of trailer after first use at Lone Star (overnight)

1. refrig does not work on gas system.
2. water connections (2) at toilet leaking. Overflow leaks into shower stall.
3. hole in front screen
4. seats not comfortable; backs low and front of cushion drops with weight of body.
5. Cannot use binoculars because of kind of glass & screens.
6. thread on water tank intake damaged, lacks safety pressure release valve.
7. gages to pressure tank not accurate.
8. step rattles and abrades metal floor
9. rear turn signal not strong enough in daytime.
10. gas lumps should be nearer table and bed.
11. curtain should pull to edge of window, not cover edges
12. top of sink too close to edge and corner.
13. Sink too small.
14. outlet from sink should be separate from toilet outlet. It is inconvenient to open the large toilet cap to just let a small amount of water ^{out of} sink. The outlet is inconvenient and hard to get at, especially if the ground is wet from sink effluents
15. Toilet outlet too low and unprotected. Most plastic joints leak.
16. Water tank should be tailored to fit area and should have gauge as to amount in tank.
17. If one carries water to tank, it is necessary to put 5-6 gals in tank to fill hot water heater tank before water is available for sink use. A valve should be placed between tank and water heater to make minimum amount of water available to sink.