

- 670728-82
14. Seats backs are uncomfortable and → height should be increased to support back and also to allow for complete coverage of bed when so used (from side to side).
 15. upper berth should be 1 foot wider to permit two people to use this bed. as it is it is too narrow for 2 people.
 16. Pipes, ^{hose} and gas pipes should follow front contour of trailer and not stick out into middle of subboards where they interfere with storage.
 18. Electrical socket should be water-proof when cord is inserted into position. Proper cord should be supplied and at least 50' longer.
 19. Butane lamp improperly placed. Electric light at sink improperly placed. Should have outlet at rear of trailer and ~~at~~ the door on outside.
 20. water intake, light box should be recessed in side of trailer.
 21. stove hood does not reach back of trailer.
 22. outlet holes for water tank drain, ice box drain ~~and~~ and ^{and} electrical wires are not sealed and allows for water ^{and} ^{and} ^{and} to enter trailer.
 23. Edged of holes with long splinters instead of clean edge.
 24. wheels not primed completely.
 25. wheel cowls not sealed to floor when fully opened.
 26. awning not far enough to cover door, & door too near top of awning.
 27. bunk bed migrates forward when brakes are applied.
 18. screws above boards supporting bed stand and digging into overriding board.
 29. upper edge of seats higher than flat top & causes friction on sliding bed steel.
 30. Installation of heater improper, ventilator interferes with door.
 31. Refug drain into angle iron
 32. drain from sink outlet down side of trailer to underneath.
 33. Cushions top hard. Bunk beds too small & hot.
 34. Gas lamp too hot
 35. angle iron under trailer not strong enough
 36. hub caps come off wheels
 37. staples rust
 38. upper window drops water on lower water when it rains