

- 51
120
- 690608-151
50. ventilators for freezer lets in strong winds, dust and snow.
 51. freezer should have single line from single tank if it to be used all the time.
 52. There should be a water valve at exit of tank to be turn off water in case of emergency.
 53. curtains blow in wind, some over fire area.
 54. back cushion on front seat too much & better without.
 55. sharp edge of windows could put out eye.
 56. subboard unfinished underneath.
 57. shower door needs better lock for travelling
 58. gas light flickers when wind blows through trailer
 59. back window is in fact a side window and water collects at base to overflow inward
 60. refrig. heats table top, sink and temp of trailer in general.
 61. axle bent toward body of trailer.
 62. spring hangers insecurely welded to body frame.
 63. refrig. light goes out when travelling or wind thru door.
 - 64.