

in the spring.

The predominant color of ocean spray is white but many inflorescences of light tan.


At 10:45 Suster, a mule deer was feeding at Bee House feeder and every other ♀ of its size or younger was challenged by erecting all hair on body to its fullest extent and would maintain this defensive posture as long as the invader remained in the area.

A ♀ mule deer 30" at shoulders fed at Bee House feeder for 12 minutes, then reclined 2 feet from feeder and remained there for 25 minutes. Another ♀ rested for equivalent time at Boundary Point.

Check The Bee, a Grand Banks boat with Stewart Marshall.

1. replaced one battery because of loose stem with equivalent 40 Fisk, 900 cold cranking hours. The old battery had been made in Seattle and this battery had not been manufactured in the last 6 years. all batteries topped with water.

2. Red no 2 was moved to port side and new battery put into 2 battery position.



3. added terminal to ground no 2. motor started on no 2 only.

3. check packing in stuffing box and retightened and joint or packing held water. Extra fiber ring supplied.

4. Tightened water hose on motor (left front)

5. now all battery terminals have been cleaned and refastened.

6. will charge over-night on automatic no 2 on charger (slow charge) and tomorrow will stop charge and then in two days will check to see if charge held.

7. replace plug at base fuel tank with valve when tanks are empty.

in tanks & 2 filters
Then release sediment + water after each fill-up. Also check primary and secondary filter system and replace elements & bleed system. after 200 hrs.

8. Repair oil pressure gauge.

9. check pulsator in fuel pump and for dirt build-up on walls of pump.

10. Bleed fuel injector for air.

