

UNIVERSITY OF KANSAS
LAWRENCE

DEPARTMENT OF PHYSICAL EDUCATION

Repairs and Needs for 1941-42

4 new toilet seats in the Women's Basement toilets.
1 new toilet seat in the faculty dressing room.

These seats are of the old automatic type that are a disgrace to this day and age.

Hockey field - If the hockey field were rolled many times this spring before the ground becomes dry or the heavy bunches of grass push up, I believe it would be in fair condition. The path across the field needs to be filled in. There has been no fence or barrier put up at the southeast corner of the field to prevent people using that path.

Tennis courts - The tennis courts were in fair condition last fall because there was little rain. There, of course, is still need of better drainage, and the courts need to be rolled more often. There is one net tightener broken which needs to be replaced.

Tennis backboard - This board needs to be 10' - 12' high to be of any use. There should be no opening in the middle. The ground must be rolled and hardened.

Swimming Pool - The lower part of the wall needs to be repainted, as well as the pipes.

Cage - The cage for equipment, towels and swimming suits should be rebuilt with more racket and cupboard space put in. The basement floor and dressing booths need repainting.

Running Track - The entire running track should be recovered from the balcony. An archery range for winter practice should be set up in the east end.

Horseshoe courts - The ground should be leveled off and new horseshoe boxes made for the six courts.

Halls - Refinish floors and repaint bulletin boards.