

"Although unable to weigh the cylinder, I would estimate that it is approximately half full (75 lbs. of chlorine). In view of the fact that the pool is to be taxed to a heavier extent in the coming year, I would recommend that Form PD 190 be filled out and filed immediately with the chlorine company in order to obtain shipment by the time the gas is needed. It has been the experience in past cases that this takes between 45 and 90 days for shipment."

I believe the chlorinator is in pretty fair working order, but the filter is of no use whatsoever in its present condition, and if anything should happen to the chlorinator we would just have to close the pool for the time of the accident which might be quite some time. Therefore, I think some measure should be taken to get this filter replaced so that all of our eggs are not placed in one basket. Mr. Eberhart says that it is impossible to count on the filter for any help the way it is at present.

Robinson Gymnasium was built in 1906, so that old filter has done service for 36 years. I would like to have authority to go forward with estimates with a view of getting a new filter in the next two years, at least.

I believe that out of the \$400 for special allotment for the pool we might replace these glazed tile and save a lot of money. I am also checking with Mr. Bayles on this tile item. We are draining the pool this week end and it will be the first time that we have had the pool drained in a year so that replacements could be made.

What is your reaction?

Very cordially yours,

Director of Physical Education,
Varsity Basketball Coach.

FCA:AH

cc-C. G. Bayles