Mr. J. Guylay, Jr., Wallace & Tiernan Sales Corporation, 426 Board of Trade Building, Kansas City, Mo.

Dear Mr. Guylay:

Our swimming peel operator and the plumber are finding a little difficulty with the vacuum relief float in the new Type MSVC Vacuum Chlerinater which we recently had installed in Robinson Gymnasium. The trouble seems to be that the float falls over and touches the bell jar, and there is nothing to release it.

I would appreciate it if you could suggest a remedy for this situation. Or perhaps if you are making a regular service trip through Lawrence some time soon you might stop by and look at it.

Very sincerely yours,

Director of Physical Education, Varsity Basketball Coach.

FCA:AH