

THE HILLYARD COMPANY

DISTRIBUTORS

Hillyard Chemical Company

BRANCHES AND WAREHOUSES IN PRINCIPAL CITIES

ESTABLISHED 1907

ST. JOSEPH · 1 · MISSOURI · U.S.A.

CABLE ADDRESS "HILCO"



IN REPLY REFER TO

- 1/ Completed finishing system - Dec - 5 - 44.
 - 2/ This floor should be taken care of according to instructions
 - 3/ This is a non skid finish
 - 4- wax should be used on this floor
 - 5- Wax is dangerous to the BB players.
 - 6 When wax is used on floor it takes a severe scrubbing to take it off which ruins the finish and removes the lines.
+ luster
- teams at the Municipal Bldg at Okla City refused to play on their floor where wax had been used for dancing. until it was scrubbed off which took ~~6~~ 6 men 10 hrs. & then was not a satisfactory playing surface. It was later necessary to re-surface it.