

Being the job operator I know you realize I have very little spare time. During the past 4 months I have done my best to handle the work assigned me, but the load has proven too heavy for one man to carry. Most of the machine work has been of a temporary or "get-by" nature, hoping to make permanent repairs when not so pressed for time. This way of doing things has resulted in the condition which now prevails. The machines are only in half running shape and things have gotten out of hand. Things have piled up until it is beyond my ability to