

Drrough

Hole plug, various sizes

Bell for outside cabin, at least adapter to hold bell.

Range finder.

need chart 17314

check and make operative the automatic bilge pump, now controlled only by manual.

varnish sink door where repaired.

space for stove: front top view  $21\frac{3}{8}$ " width,  $21\frac{5}{8}$ " depth; from front view  $21\frac{3}{8}$ " width, 24" height, depth  $21\frac{5}{8}$ ".

AT&T call card no. 206-468-2454-3077