

METHODS FOR THE

DETERMINATION OF

THE AMOUNT OF WATER IN THE AIR

BY THE USE OF THE

PSYCHROMETER

AND THE

WET-BULB THERMOMETER

BY

W. M. BARTON

U. S. DEPARTMENT OF AGRICULTURE

WASHINGTON, D. C.

1911

U. S. GOVERNMENT PRINTING OFFICE

1911