

Replacing YOUR BASKETBALL BACKBOARDS

Substitution of the new modified backboard for the old board presents several minor installation problems. For example, the majority of backboards are of the wall or ceiling suspended type or wall attached type. In other special type installations, the supports are attached to the ends of the 6' wide backboard. The new backboard with the new (see following pages) design of supports requires supports to accommodate the angle.

The above task does not present any problem if a local mechanic cannot easily handle. However, Universities having shop facilities should be consulted for making the necessary adjustments of an existing installation.

This manual has been compiled for the benefit of the individual customer and prospective customer responsible for the substitution of the new, modified Basketball Backboard for existing Equipment and is presented with the compliments of Fred Medart Manufacturing Co. —

St. Louis.

