

no 4 - hole

- Both trees need removing in
middle of fairway - drainage
tile done green just below old
log cabin - sand and oil and new
base construction - fairway seed
estimate 40.00

no 5 - hole -

new fairway fopping for hole
distance - felling in of swamps and
road across fairway - 30 load
of soil and possibly all new seeded
fairway - green base of clay and oil
and sand and oil top - 00.00

no 6 - good shape -

oil and sand on the green - 20
ft tile and leveling fairway only
estimate 15.00

Total estimate of reconstruction of
the course - 5410.00

Rest would be labor and
maintenance costs only 1400.00
5410.00

Glenn Patman