

THE STANDARD POOL CLEANER COMPANY INC
MANUFACTURERS TUEC POOL CLEANERS
1320 GREENFIELD AVE S. W.
CANTON, OHIO

September 9, 1942

University of Kansas
Lawrence, Kansas.

Attention: Mr. F. C. Allen, Dir. of Phy. Ed.

Gentlemen:

In reply to your letter of September 5th we are glad to know you have had your pump repaired.

Our inlet is threaded with a standard 2" male pipe thread so this can be attached directly to the intake of your pump. The other end will take the friction male terminal we furnish on the hose.

In regard to the discharge, we suggest that you use 1 1/2" pipe at least direct from the pump, 2" would be a little better but 1 1/2" will do as our hose is 1 1/2" inside diameter.

We have no discharge hose but no doubt you could get some old fire hose that will serve your purpose. We can not advise the best method to connect this to the pump and discharge pipe but your plumber can do this for you.

We suggest that you get your order through as soon as possible and give us the best priority you can get. We can not produce new cleaners on anything less than an A-1-K priority and on a government contract only. We can sell what we have made up on less than that as long as they last we can ship but on a government contract we can produce the cleaner so if the government will help you we would appreciate that.

Yours very truly,

THE STANDARD POOL CLEANER COMPANY

Carl Amiet
Sales Manager

Carl Amiet/g